


FIG. 1

2002

FIG. 2






FIG. 3




FIG. 4




Fig. 5




Figure 6A




Fig. 6B




FIG 6C




Figure 7




Fig. 8

Figure 9




Figure 10





FIG. 11






Figure 12

044063-1150

200

505

1600




Figure 13




Figure 14

09440693-11699

15A
Figure 15A





Figure 15B






Figure 16




Figure 17




Figure 18




Figure 19




Figure 20




Figure 21

Figure 22




Figure 23

Key		Value	
1910	UserID	RicohCorp-user1	
	ApplicationID	MB	
	CumulativeUse	45	
	StartTime	16:10:45 PM Jun 21, 1999	
1900	•	•	
	•	•	
	•	•	

map<string, string> for target application #1

Key		Value	
1910	UserID	RicohCorp-user2	
	ApplicationID	Diagnosis	
	CumulativeUse	6	
	StartTime	16:10:45 PM Jun 15, 1999	
1900	•	•	
	•	•	
	•	•	

map<string, string> for target application #2

Figure 24




Figure 25

